CORRES. CONTROL		
OUTGOING LTR. NO.		
DOE ORDER # 4700.1		
02-RF-01795		
DIST.	LTR	8
BRAILSFORD, M.D.		
FERRERA, D.W.		L
FERRI, M.S.	_	L
MARTINEZ, L. A.	L	L
PARKER, A.	_	L
POWERS, K.	-	Ļ
SCOTT, G.K. SHELTON, D.C.	₹Z	Ŀ
SPEARS, M.S.	Δ	┝
TRICE, K.D.	-	H
TUOR, N. R.		H
700141010	Н	-
**************************************	Н	-
	\vdash	r
AGUILAR, P.		_
ALBIN, C.		Г
AUBLE, M.		
BEAN, C.		
BUTLER, J. L.		
CERCLA AR (T130G)		_
CLARK, D		_
DIETERLE, S.	_	_
DORR, K.		
FREIBOTH, C.	٠	_

GUTHRIE V HUMISTON, T.

KEHLER, K

KONWINSKI, G.

MARSCHALL, J.R. MARTIN, D.

KNAPP, S.

MYERS K

NESTA, S. NORTH, K OLMER, R.

OMAN, K.

TRAFFIC PATS/130

PRIMROSE A

ROSENMAN, A

CORRES.CONTROL ADMIN RECREVOSO

NYDER, D.P.



August 9, 2002

02-RF-01795

Joseph A. Legare Assistant Manager for Environment and Stewardship DOE, RFFO

FACILITY DISPOSITION ROCKY FLATS CLEANUP AGREEMENT (RFCA) STANDARD OPERATING PROTOCOL (RSOP) - FEG-015-02

The Facility Disposition Rocky Flats Cleanup Agreement (RFCA) Standard Operating Protocol (RSOP) requires that DOE notify the Lead Regulatory Agency (LRA) prior to implementing work activities pursuant to this document. The Rocky Flats Environmental Technology Site (RFETS) received concurrence from the Colorado Department of Health and the Environment (CDPHE) that B442L/W, B662, and B663 were Type 1s. Subsequently, the facilities were further separated into Type 1 for the free releasable upper portions, and Type 2 for the remaining contaminated slabs, and pipes. The Facility Disposition RSOP allows for items not meeting the free release criteria to be transitioned to Environmental Restoration (ER) to achieve overall integration from D&D through ER.

The purpose of this Notification is to invoke this RSOP for the work that has been done to date at B442, B662 and B663, and activities that have been transitioned to the ER organization to be implemented pursuant to the ER RSOP (ref. Contact Record dated August 8, 2002). At B442, the slab and the sewer pipe were left in place after building demolition because of fixed contamination. ER has subsequently removed the B442 slab and removed the sewer pipe to greater than six feet below grade (ER Notice #02-06). Because the slabs at B662 and B663 are contaminated, they were left in place to be removed by ER under the ER RSOP (ER Notice # 02-07).

The LRA will have 14 days to review this notification letter and provide feedback.

If you have any questions or require additional information, please contact Steve Nesta at X6386.

INCLASSIFIED ONFIDENTIAL tuk E. Th Frank E. Gibbs

SIGNATURE:

CLASSIFICATION:

REPLY TO REP CC NO .:

CTION ITEM STATUS PARTIALIOPEN

CLOSED

SMN:pvt

Org. and 1 cc - Joseph A. Legare

Remediation, Industrial D&D, and Site Services

Deputy Project Manager

PRIG. & TYPIST INITIALS: SMN:pvt

-46469/Rev 9/941

Steve Tower

Kaiser Hill Company, L.L.C.

Rocky Flats Environmental Technology Site, 10808 Hwy. 93 Unit B, Golden CO 80403-8200 ◆ 303-966-7000

ADMIN RECORD ADMIN RECORD